



**Associated British Ports - Lowestoft**

**No 14  
2018**

## **NOTICE TO MARINERS**

### **LOWESTOFT APPROACHES**

### **SOUTH SEWER BUOY – OFF STATION**

Mariners and Port Users are advised that the South Cardinal Buoy - Position 52° 28.84'N 01° 46.25'E has been removed from its station for repairs.

The East Cardinal Buoy – Position 52° 28.89'N 01° 46.24'E remains on station and its Navigation Light has been restored to normal service i.e.

VQFI (3) 5 secs.

Further notification will be provided when the South Sewer Buoy has been restored to its station.

Local Notices to Mariners No. 37/2017 and No.13/2018 are both cancelled by this notice

For further information please contact Lowestoft Port Control, (VHF Ch.14, Tel. 01502 572286).

**Harbour Master**

**11<sup>th</sup> May 2018**

**Notices to Mariners Currently in Force: 2006** No.5 **2007** No.13 **2009** No.19 **2011** No.7, No.10, No.19 **2012** No.3, **2013** No.17, No.19, **2015** No.10, No.24 **2016** No.12, **2017** No.5, No.9a, No.12, No.22, No.24, No.32, No.34, No.35, **2018** No.1, No.11, No.14

(See also [http://www.abports.co.uk/Marine/Short\\_Sea\\_Ports/Lowestoft/Notices\\_to\\_Mariners/](http://www.abports.co.uk/Marine/Short_Sea_Ports/Lowestoft/Notices_to_Mariners/))