

Broads Authority

Cultural Heritage Survey Sheet

Norton Marshes Drainage Mill



Cultural Heritage ID No: -	Inspection date(s): - Ben Hogg & Prue Smith 09/11/11	Location, Address and Grid Ref: -	
Listed Grade: - (N/L, N/PL) Local list	Fragility: - 1 (1 – 3)	Vulnerability: - 2 (1 – 3)	
Photographs: -IMG 4989 - 4996		BAR Risk Grade: - (A – F)	N@R
<p>Description/Context: - Drainage Mill. Tarred red brick tower mill. Small to medium size, 4 storeys with white painted boat shaped cap and gallery. Black stained horizontal boarded scoop wheel housing, small 20c single storey extension to riverside, also stained boarding on red brick plinth with red pantile roof. Part red brick drainage lane, possibly re-constructed. Ground floor timber boarded door with glazed light over on opposite side to river, 4 first floor windows, 2 windows to second and third floors, all timber with small panes. Third floor windows have arched heads. Converted to residential use. All in good condition. 20c red brick pump house nearby.</p> <p>A.C. Smith notes in 1989 that mill built in 1863, no internal machinery remains and that no wheel remains in reconstructed scoop wheel housing.</p>			
<p>Significance: - A well restored example of a drainage mill in a prominent position beside the river Yare. The residential conversion has preserved the external character of the building.</p>			
<p>Threat posed: - No immediate threat.</p>			
<p>Conclusion / Recommendation: -</p> <p>Immediate:</p> <ul style="list-style-type: none"> • <p>Medium term</p> <ul style="list-style-type: none"> • <p>Long term:</p>			