

Broads Authority

Cultural Heritage Survey Sheet

Charlie Water's Mill, Acle



Cultural Heritage ID No: -	Inspection date(s): - Ben Hogg & Prue Smith 23/11/11	Location, Address and Grid Ref: -	
Listed Grade: - (N/L, N/PL) Local list	Fragility: - (1 – 3) 2	Vulnerability: - (1 – 3) 2	
Photographs: -IMG 5036 - 5040		BAR Risk Grade: - (A – F)	N@R
<p>Description/Context: - Remains of battered red brick tower reduced to two storeys with flat mineral felt roof, recently renewed. Double doorway on riverside crudely closed with concrete blockwork, semi-circular window opening and remains of c.i. window above, 20c double timber doors on opposite side with similar window over. Larger double opening similarly blocked to north. Needs decorating and rainwater goods. Cracking to brickwork above r'side door way, considerable vegetation growth on south side, possible due to lack of r'wter goods. New outfall pipe and gearing box cabinet adjacent.</p>			
<p>Significance: - the remains of one of an important group of drainage mills in the Broads area and a feature in the landscape.</p>			
<p>Threat posed: - Damage to brickwork from water and vegetation.</p>			
<p>Conclusion / Recommendation: -</p> <p>Immediate:</p> <ul style="list-style-type: none"> • <p>Medium term</p> <ul style="list-style-type: none"> • <p>Long term:</p>			