

Broads Authority

Cultural Heritage Survey Sheet

Randall's Mill, Calthorpe



Cultural Heritage ID No: -	Inspection date(s): - Ben Hogg & Prue Smith 29/11/11	Location, Address and Grid Ref: -	
Listed Grade: - (N/L, N/PL) Local list	Fragility: - (1 – 3)	3	Vulnerability: - (1 – 3) 3
Photographs: -IMG 5045 - 5049		BAR Risk Grade: - (A – F)	N@R
Description/Context: - Substantial red brick tower mill, reduced to 3 storeys with conical corrugated iron roof and finial. Timber door and frame, two opposing timber first floor windows. Brickwork spalling with substantial vegetation growth. Adjoining brick shed/living accommodation not inspected. Drainage lane intact. Substantial remains of brick abutments, arches etc.			
Small modern brick pump house behind and 2 small wind turbines in field beyond.			
Significance: - the substantial remains of one of an important group of drainage mills in the Broads area and a feature in the landscape.			
Threat posed: - Potential continued erosion of brickwork and damage to brick from vegetation growth.			
Conclusion / Recommendation: -			
Immediate: <ul style="list-style-type: none"> • 			
Medium term <ul style="list-style-type: none"> • 			
Long term:			