

Broads Authority

Cultural Heritage Survey Sheet

Somerleyton Marshes Drainage Mill remains



Cultural Heritage ID No: -	Inspection date(s): - Ben Hogg & Prue Smith 23/11/11	Location, Address and Grid Ref: -	
Listed Grade: - (N/L, N/PL) Local list	Fragility: - (1 – 3) 1	Vulnerability: - (1 – 3) 1	
Photographs: -IMG 5012 - 5023		BAR Risk Grade: - (A – F)	A
Description/Context: - Small formerly tarred red brick tower mill reduced to one storey with conical timber and corrugated iron roof in poor condition with lead pinnacle. Opposing doorways, that to riverside bricked up at base. Turbine survives in small corrugated iron pump shed adjacent to east, also in poor condition. Larger 20c brick and pantile electric pump shed between mill and river – possibly not in use. Door frame, but door missing. Very poor condition severe cracking to brickwork to north and east. Arch above south doorway and roof verge in poor condition.			
Significance: - the remains of one of an important group of drainage mills in the Broads area and a feature in the landscape.			
Threat posed: - Vegetation growth and brickwork decay. Water ingress through filing roof, doors missing.			
Conclusion / Recommendation: -			
<p>Immediate:</p> <ul style="list-style-type: none"> • <p>Medium term</p> <ul style="list-style-type: none"> • <p>Long term:</p>			