

Broads Authority

Cultural Heritage Survey Sheet

Barton Broad Drainage Mill, Catfield



Cultural Heritage ID No: -	Inspection date(s): - Ben Hogg & Prue Smith 29/11/11	Location, Address and Grid Ref: -	
Listed Grade: - (N/L, N/PL) Local list	Fragility: - (1 – 3) 1	Vulnerability: - (1 – 3) 2	
Photographs: -IMG 5064 - 5068		BAR Risk Grade: - (A – F)	B
Description/Context: - Red brick stump of tower mill. Reinforced brickwork (?) flat roof in poor condition. Door missing. In poor condition – brickwork spalling and breaking down to RHS door. Ivy growth to roof (may have been partially killed?)			
Significance: - the substantial remains of one of an important group of drainage mills in the Broads area and a feature in the landscape.			
Threat posed: - Historic and on-going neglect. Vegetation growth and erosion of brickwork. Potential roof failure. Redundancy.			
Conclusion / Recommendation: -			
Immediate: <ul style="list-style-type: none"> • 			
Medium term <ul style="list-style-type: none"> • 			
Long term:			