

Broads Authority

Cultural Heritage Survey Sheet

Old Hall Mill, Belaugh

Image not currently available.

Cultural Heritage ID No: -	Inspection date(s): - Ben Hogg	Location, Address and Grid Ref: -
Listed Grade: - (N/L, N/PL) Local list	Fragility: - (1 – 3) 1	Vulnerability: - (1 – 3) 1
Photographs: -	BAR Risk Grade: - (A – F) B	
Description/Context: - Red brick tower mill, 4 storeys. Pump engine shed adjoining Mill. Significant vegetation growth causing damage to brickwork.		
Significance: - One of an important group of drainage mills in the Broads area and a feature in the landscape.		
Threat posed: - Decay of fabric through lack of on-going maintenance. Vegetation growth and lack of roof covering accelerating decay.		
Conclusion / Recommendation: - Immediate: Immediate removal of vegetation growth and provision of temporary cap recommended. • Medium term • Long term:		