

Broads Authority

Cultural Heritage Survey Sheet

Engine House, Strumpshaw



| | | | |
|---|---|--|------------|
| Cultural Heritage ID No: - | Inspection date(s): - Ben Hogg & Prue Smith 09/11/11 | Location, Address and Grid Ref: - | |
| Listed Grade: - (N/L, N/PL) Local list | Fragility: - 1 (1 – 3) | Vulnerability: - 2 (1 – 3) | |
| Photographs: -IMG 4971 - 4978 | | BAR Risk Grade: - (A – F) | N@R |
| Description/Context: - Single storey engine house, corrugated asbestos sheeting roof with gault (white) brick to north, east and south, soft red brick to west side. Two semi-circular headed windows to river side (south) with remains of c.i. frames indicating small panes, later offset double timber doors to north elevation. Decorative 'tudor rose' patress plates to front and rear. Closed openings at lower level to south and east. Adjacent on riverside, tall octagonal gault brick chimney on square base with cast iron string course and circular c. i. cap. Cracking to brickwork, ivy growth extends to roof on north west corner. Some earlier b'work repairs in Fletton bricks, some spalling and open joints to w redbrick elevation. | | | |
| Significance: - One of a small but important group of engine pump houses on the Broads and a significant element in the landscape. Part of the development of the drainage of the Broads area, after the wind powered drainage mills. | | | |
| Threat posed: - Lean to chimney. Vegetation growth, structural instability. | | | |
| Conclusion / Recommendation: - | | | |
| Immediate: <ul style="list-style-type: none"> • | | | |
| Medium term <ul style="list-style-type: none"> • | | | |
| Long term: | | | |