

Broads Authority

Cultural Heritage Survey Sheet

Middle Marsh Drainage Mill, Catfield



Cultural Heritage ID No: -	Inspection date(s): - Ben Hogg & Prue Smith 22/02/12	Location, Address and Grid Ref: -	
Listed Grade: - (N/L, N/PL) Local list	Fragility: - (1 – 3) 3	Vulnerability: - (1 – 3) 3	
Photographs: -IMG 5207 – 5217		BAR Risk Grade: - (A – F)	N@R
Description/Context: - Small red brick tower mill with medium batter. Large aperture in wall from base to over half way up the tower, ground floor door opening opposite also enlarged upwards. Small opening on side at ground level. No cap, but recently re-roofed in lead and timber, curb and other brickwork repaired and simple RW drainage installed. Good condition, considering past damage to structure.			
Significance: - One of an important group of drainage mills in the Broads area and a prominent feature in the landscape.			
Threat posed: - No immediate threat, recently stabilised.			
Conclusion / Recommendation: - Immediate: • Medium term • Long term:			