

# Broads Authority

## Cultural Heritage Survey Sheet

### Ludham Bridge North Drainage Mill, Ludham



<b>Cultural Heritage ID No:</b> -	<b>Inspection date(s):</b> - Ben Hogg & Prue Smith 29/11/11	<b>Location, Address and Grid Ref:</b> -	
<b>Listed Grade:</b> - (N/L, N/PL) Local list	<b>Fragility:</b> - (1 – 3)      2	<b>Vulnerability:</b> - (1 – 3)      2	
<b>Photographs:</b> -IMG 5091 – 99		<b>BAR Risk Grade:</b> - (A – F)	<b>A</b>
<b>Description/Context:</b> - Small red brick tower mill with base converted to WW2 'pillbox' and part of wooden frame on top. Various door and window openings the lower ones altered for gun ports. 3 Storeys, tower leans slightly, about 20 ft high to iron curb, base approx. Diameter 12' 4" including 18" thick walls. Internal inspection not possible. In poor condition especially the brickwork around the door and first floor window openings and under the iron curb where it is missing in parts.			
<b>Significance:</b> - The substantial remains of one of an important group of drainage mills in the Broads area and a feature in the landscape.			
<b>Threat posed:</b> - Damage to brickwork from weather and vegetation. Potential for vandalism.			
<b>Conclusion / Recommendation:</b> - <b>Immediate:</b> • <b>Medium term</b> • <b>Long term:</b>			