

Broads Authority

Cultural Heritage Survey Sheet

Palmers Mill, Upton Marshes



| | | | |
|---|---|--|------------|
| Cultural Heritage ID No: - | Inspection date(s): - Ben Hogg & Prue Smith 23/11/11 | Location, Address and Grid Ref: - | |
| Listed Grade: - (N/L, N/PL) Local list | Fragility: - 3 (1 – 3) | Vulnerability: - 3 (1 – 3) | |
| Photographs: -IMG 5032 - 5035 | | BAR Risk Grade: - (A – F) | N@R |
| <p>Description/Context: - Hollow post mill, restored to working order. Four single-shuttered spring sails, small boarded buck (on top of main post), twin tail vanes and ladder, all white painted timber. Main post 11” x 10” section, approximately 12ft high and quarter bars, all black tarred timber on sunk piers. Iron piston and 10” inside diameter cylinder. In good condition, but could do with decorating in the near future. Removed when derelict from original site near Acle in 1976 and restored on present site 1978-79 by Richard Seago. First pumped water 9 July 1980.</p> | | | |
| <p>Significance: - An unusual and important developmental stage in the history of drainage of the Broads marshes and a significant element in the landscape.</p> | | | |
| <p>Threat posed: - No immediate threat.</p> | | | |
| <p>Conclusion / Recommendation: -</p> <p>Immediate:</p> <ul style="list-style-type: none"> • <p>Medium term</p> <ul style="list-style-type: none"> • <p>Long term:</p> | | | |