

Broads Authority

Cultural Heritage Survey Sheet

Buckenham Ferry Drainage Mill



Cultural Heritage ID No: -	Inspection date(s): - Ben Hogg & Prue Smith 09/11/11	Location, Address and Grid Ref: -	
Listed Grade: - (N/L, N/PL) Local list	Fragility: - 1 (1 – 3)	Vulnerability: - 2 (1 – 3)	
Photographs: -IMG 4966 - 4970		BAR Risk Grade: - (A – F)	N@R
Description/Context: - Red brick (formerly tarred) tower drainage mill shell, medium size, 4 storeys, leaning and 'kinked' near top indicating movement pre-dated later raising. Kerb intact. Partial timber and concrete flat roof. Window openings at first, second & third floor, no joinery. 20c steel door in enlarged opening partly closed with Fletton bricks. Modern machinery internally, and possibly remains of original floors. Rendered pump enclosure and electrical equipment nearby. Some remains of drainage lanes. Some brickwork spalling and open joints, pigeon infestation. Lack of roof covering an issue.			
Significance: - the substantial remains of one of a group of drainage mills in the Broads area and a feature in the landscape.			
Threat posed: - No immediate threat, but lack of roof covering will lead to long term damage. Bird ingress an issue.			
Conclusion / Recommendation: -			
<p>Immediate:</p> <ul style="list-style-type: none"> • <p>Medium term</p> <ul style="list-style-type: none"> • <p>Long term:</p>			